FY 2015 MSCC Budget Allocation Recommendation

Requirement - Requirement Name	Requirement - Priority 0- Currently Critical	Requirement Resource Capital Improvement	Estimated Cost	
Fire Alarm System: Beyond Rated Life			\$	660,052.00
Subtotal - Life Safety			\$	660,052.00
Substructure: Concrete Spalling Rusting Rebar, Catacombs	0- Currently Critical	Capital Improvement	\$	3,438,041.00
Roadways: Aged Pavement	0- Currently Critical	Capital Improvement	\$	2,180,096.00
Exterior Stairs: Mortar Loss (South Elevation)	0- Currently Critical	Capital Improvement	\$	1,448,457.00
Exterior Stairs: Damage	1- Potentially Critical	Capital Improvement	\$	70,835.00
Exterior Plaza: Reconstruction	1- Potentially Critical	Capital Improvement	\$	2,890,197.00
Windows: Malfunctioning Gaskets and Hardware	1- Potentially Critical	Capital Improvement	\$	697,391.00
Exterior Wall: Cracking Limestone (Cupola)	1- Potentially Critical	Capital Improvement	\$	498,895.00
Exterior Wall: Limestone Cracking (Main Body)	1- Potentially Critical	Capital Improvement	\$	28,209,361.00
Subtotal - Exterior			\$	39,433,273.00
Passenger Elevators 1 to 6: Beyond Rated Life	2- Necessary - Not Yet Critical	Capital Improvement	\$	1,986,987.00
Standpipes and Hose Connections Aged	2- Necessary - Not Yet Critical	Capital Improvement	\$	129,506.00
Hot Water Heating System Incomplete	2- Necessary - Not Yet Critical	Capital Improvement	\$	196,462.00
Ceiling Finishes: Historic Restoration	3- Recommended	Capital Improvement	\$	7,230,046.00
Subtotal - Miscellaneous			\$	9,543,001.00
Interior Lighting Equipment: Beyond Rated Life	2- Necessary - Not Yet Critical	Energy	\$	952,666.00
Lighting and Branch Wiring: Occupancy Sensors Insufficient	3- Recommended	Energy	\$	47,674.00
Subtotal - Energy			\$	1,000,340.00
Stade ADA Constitute	4- Does Not Meet Current Codes /	Controller		350,000,00
Study - ADA Compliance	Standards	Capital Improvement	\$	250,000.00
Subtotal - ADA			\$	250,000.00
TOTAL BASE COST - CI NEEDS			Ś	50,886,666.00